

## Superfund Site Strategy Recommendation

Region 6

Site Name: Wood-Protection Co. Site Number: TXD05934S116

Alias Site Name(s): \_\_\_\_\_

Address: 5151 South Loop ECity/County or Parish/State/Zip: Houston/HARRIS/TX/77033

## Recommendation:

☐ 1. No further action needed; no hazardous waste problem.☒ 2. No further remedial action planned under Superfund; site would not score high enough using the Hazard Ranking System to be considered for the National Priorities List.☐ 3. No further remedial action planned Under Superfund; action may be appropriate under other authority: RCRA \_\_\_\_\_ NPDES \_\_\_\_\_ SPCC \_\_\_\_\_  
404 \_\_\_\_\_ TSCA \_\_\_\_\_ UIC \_\_\_\_\_ SMCRA \_\_\_\_\_ State \_\_\_\_\_  
Other \_\_\_\_\_☐ 4. Further pre-remedial investigative action needed under Superfund:PA \_\_\_\_\_  
SSI \_\_\_\_\_ Priority: High \_\_\_\_\_ Medium \_\_\_\_\_  
LSI \_\_\_\_\_  
Other \_\_\_\_\_  
To be performed by \_\_\_\_\_

Discussion: This is an active wood-treating facility that appears to be a RCRA small quantity generator only. The facility reports that no hazardous waste have been generated since 1979. The facility has been in operation since 1952; it appears that chromated copper arsenate has been the primary chemical used. Waste handling practices from 1952 to 1979 are unknown. This site does not appear to be a potential NPL candidate, due to insufficient target populations; therefore, no further activity under CERCLA is recommended.

SUPERFUND FILE

APR 29 1992

REORGANIZED

Copies to (please list): <sup>cc:</sup> 6 H-HORecommended By: J. Delgado (S) (HES)Date: 9/8/88Approved By: Presley R. TalbotDate: 9-16-88

9418204

